



Type TDG 250 ND 5 = 20 mm²

| Connection A | Hex SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|---------------|--------|---------|------|------|--------|-----------------------|-------------|
| M 16 x 1,5 o. | 22 | | 92 | 23 | 5 NBR | 250 | 250W |




Type TDG 250 ND 6 = 28 mm²

| Connection A | Hex SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|--------------|--------|---------|------|------|--------|-----------------------|-------------|
| G 1/4 i. | 22 | | 53 | 23 | 6 NBR | 250 | 250 |
| G 1/4 i. | 22 | | 53 | 23 | 6 NBR | 250 | 250RF 1) |




Type TDG 500 ND 11 = 95 mm²

| Connection A | Hex SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|--------------|--------|---------|------|------|--------|-----------------------|-------------|
| G 1/2 i. | 32 | | 71 | 35 | 11 NBR | 250 | 500 |
| G 1/2 i. | 32 | | 71 | 35 | 11 NBR | 250 | 500RF 1) |




Type 1

| | | | | | | | |
|----------|----|--|----|----|--------|-----|------|
| G 1/2 i. | 32 | | 73 | 35 | 11 NBR | 250 | 500B |
|----------|----|--|----|----|--------|-----|------|




Type 1A

| | | | | | | | |
|-------------|----|--|----|----|--------|-----|-------|
| M 18x1,5 o. | 32 | | 73 | 35 | 11 NBR | 250 | 500W |
| M 26x1,5 o. | 32 | | 77 | 35 | 11 NBR | 250 | 500W2 |
| M 18x1,5 o. | 32 | | 73 | 35 | 11 NBR | 250 | 500W3 |




Type 2

| | | | | | | | |
|--------------|----|--|----|----|--------|-----|-----------|
| M 22x1,5 o. | 32 | | 81 | 35 | 11 NBR | 250 | 500W5 |
| M 24x1,5 o. | 32 | | 81 | 35 | 11 NBR | 250 | 500W6 |
| 7/8-14UNF o. | 32 | | 95 | 35 | 11 NBR | 250 | 500-30 |
| 7/8-14UNF o. | 32 | | 87 | 35 | 11 NBR | 250 | 500-32 1) |



Type 3

| | | | | | | | |
|----------------|----|--|-----|----|--------|-----|--------|
| 7/8-14UNF o. | 32 | | 92 | 35 | 11 NBR | 250 | 500-31 |
| 11/16-12UNF o. | 32 | | 101 | 35 | 11 NBR | 250 | 500-33 |



Type 3A


Type TDG 750 ND 17 = 225 mm²

| Connection A | Hex SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|--------------|--------|---------|------|------|--------|-----------------------|-------------|
| G 3/4 i. | 40 | | 80 | 35 | 17 NBR | 250 | 750-QC |
| G 3/4 i. | 40 | | 80 | 35 | 17 NBR | 250 | 750RF 1) |




Type TDG 1000 ND 22 = 380 mm²

| Connection A | Hex SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|--------------|--------|---------|------|------|--------|-----------------------|-------------|
| G 1 i. | 50 | | 94 | 43 | 22 NBR | 200 | 1000-QC |
| G 1 i. | 50 | | 94 | 43 | 22 NBR | 200 | 1000RF 1) |




Type TKR ND 6 = 28 mm up to ND 22 = 380 mm²



| Connection | Hex A SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|------------|----------------|------------|---------|---------|--------|--------------------------|--------------|
| G 1/4 o. | 27 | 19 | 88 | 29 | 6 NBR | 350 | 2KRAW13IW13 |
| G 3/8 o. | 30 | 22 | 87 | 33 | 9 NBR | 350 | 3KRAW17IW17 |
| G 1/2 o. | 32 | 27 | 95 | 35 | 11 NBR | 350 | 5KRAW21IW21 |
| G 3/4 o. | 45 | 32 | 109 | 50 | 17 NBR | 350 | 7KRAW26IW26 |
| G 1 o. | 50 | 40 | 117 | 55 | 22 NBR | 250 | 10KRAW33IW33 |

Type TKR 90° ND 6= 28 mm up to ND 22 = 380 mm²



| Connection | Hex A SW | Hex1 SW | L mm | D mm | NDSeal | Working press. in bar | Part Number |
|------------|----------------|------------|---------|---------|--------|--------------------------|------------------|
| G 1/4 o. | 32 | 19 | 93 | 35 | 6 NBR | 350 | 2KRAW13IW13S-90 |
| G 3/8 o. | 38 | 22 | 95 | 41 | 9 NBR | 350 | 3KRAW17IW17S-90 |
| G 1/2 o. | 41 | 27 | 108 | 45 | 11 NBR | 350 | 5KRAW21IW21S-90 |
| G 3/4 o. | 55 | 32 | 125 | 60 | 17 NBR | 350 | 7KRAW26IW26S-90 |
| G 1 o. | 65 | 40 | 139 | 72 | 22 NBR | 250 | 10KRAW33IW33S-90 |